

12.3.1 38v2
1-16-03

LONGVIEW FIBRE COMPANY

MAIN OFFICE AND MILLS - LONGVIEW, WASHINGTON 98632
1-360-425-1550



January 16, 2003

Washington Department of Ecology
Hazardous Waste Information
P.O. Box 47658
Olympia, WA. 98504-7658

Dear Sir or Madame:

Please find enclosed the Washington State Department of Ecology Dangerous Waste Verification Forms (VF) for calendar year 2002. The VF's cover dangerous waste activities at Longview Fibre Company's Longview mill site, Seattle Box Plant, Yakima Box Plant, and the sawmill in Leavenworth. Other report files for the Longview facility were sent to the WDOE by E-mail attachments.

Please call me at (360) 575-5578 if you have any questions pertaining to these reports. Our fax number is (360) 575-6110.

Sincerely,


A handwritten signature in cursive script that reads "Steve E. Frase".

Steve E. Frase
Solid Waste Engineer

CC: Jim Mantel, Seattle
Leo Valladares, Yakima
George Boober, Winton
TEV/ADW, SEF, file.



LFC000737



Dangerous Waste Annual Report Verification Form

2002

Washington State Department of Ecology
Hazardous Waste Information
P. O. Box 47658
Olympia, WA 98504-7658
(800) 874-2022 (within state)
(360) 407-6170

For Ecology Use Only - Date Received :

Form	Review	HWIMSy Entry	Verification
VF			
GM			
WR			
OI			

Site Location Information

RCRA Site ID: WAD 009 282 161

Current Company Name: Longview Fibre Co

Site Location: 5901 E MARGINAL WY S

City/State/Zip: SEATTLE, WA 98134

County: KING

Dept. of Revenue Tax Registration Number: 840-000-74

NAICS: 322211

**This Report is
Due
No Later Than
March 3, 2003**

All information listed below is required. If information is missing or incorrect, please enter the changes in the right hand column.

1a The mailing address for this site is:

Name: Longview Fibre Co
Mail Address: PO Box 24867
SEATTLE, WA 98124-0867

1b

Name: _____
Mail Address: _____

2a The legal company/agency owner is:

Name: Longview Fibre Co
Mail Address: PO Box 639
LONGVIEW, WA 98632-7411
Work Phone: (360)425-1550 Ext: _____

2b

Name: _____
Mail Address: _____
Work Phone: _____ Ext: _____

Did the company ownership change in 2002?

☐ Yes Date: _____ (continue to the right):
☒ No (go to 3a):

I represent the:

☐ Current Company Owner
☐ Previous Company Owner

This report covers waste activity for:

☐ Entire year
☐ My term of ownership only

3a The land owner of this site is:

Name: Longview Fibre Co
Mail Address: PO Box 639
LONGVIEW, WA 98632-7411
Work Phone: (360)425-1550 Ext: _____

3b

Name: _____
Mail Address: _____
Work Phone: _____ Ext: _____

4a The contact for site visits and inspections is:

Name/Title: Tom Craig
Mail Address: 5901 E MARGINAL WY S
SEATTLE, WA 98134-2414
Work Phone: (206)762-7170 Ext: _____
E-Mail Address: _____

4b

Name/Title: _____
Mail Address: _____
Work Phone: _____ Ext: _____
E-Mail Address: _____

5a The contact for annual report forms is:

Name/Title: Steve Frase
Mail Address: PO Box 639
LONGVIEW, WA 98632-7411
Work Phone: (360)575-5578 Ext: 5578
E-Mail Address: _____

5b

Name/Title: _____
Mail Address: _____
Work Phone: _____ Ext: _____
E-Mail Address: _____

STATE OF WASHINGTON
DEPARTMENT OF ECOLOGY

Northwest Regional Office • 3190 160th Avenue SE • Bellevue, Washington 98008-5452 • (425) 649-7000

April 18, 2003

CERTIFIED MAIL

7002 3150 0004 8540 3763

Mr. Belton Rogers
Longview Fibre Co.
5901 E. Marginal Way S.
Seattle, WA 98134

RE: Dangerous Waste Compliance Inspection at Longview Fibre Co.
RCRA ID# WAD 009 282 161 on February 26, 2003

Dear Mr. Rogers:

Thank you for your time during the compliance inspection. The purpose of this inspection was to determine the facility's level of compliance with the Washington State Dangerous Waste Regulations (Chapter 173-303 WAC). These regulations establish a system for safe and responsible management of dangerous waste. Based on my visit, it appears that dangerous waste compliance issues have been well addressed at your site. I did not observe any areas of non-compliance with the Dangerous Waste Regulations. A report of the inspection is enclosed for your records.

Please do not hesitate to call me at (425) 649-7277 should you have questions or require clarification of any of the information.

Sincerely,

Victoria Sutton

Victoria Sutton, Hazardous Waste Compliance Inspector
Hazardous Waste and Toxics Reduction Program

VS:dh

Enclosure(s)



**Washington Department of Ecology
Hazardous Waste & Toxics Reduction Program
Compliance Report**

Site : Longview Fibre Co. RCRA ID#: WAD 009 282 161
Inspection Date: February 26, 2003
Site Contacts: Belton Rogers
Phone: (206) 762-7170
Site Location: 5901 E. Marginal Way S.
Seattle, WA 98134
At This Site Since: 1950's SIC#: 2653
Generator/Site Status: Small Quantity Generator

Ecology

Lead Contact: Victoria Sutton Phone: (425) 649-7277 FAX : (425) 649-7098
Other Representatives: Byung Maeng
Report Date: April 18, 2003
Report By: Victoria Sutton

Victoria Sutton

(Signed)

4-21-03

(Date)

Facility Background:

Longview Fibre Corp. manufactures corrugated cardboard boxes for the food and wine industry. At this plant the boxes are prepared and printed with water based ink. The main waste stream is dust from the cardboard which is disposed into the solid waste dumpster. The facility shows that they do not generate regulated dangerous waste on their Annual Dangerous Waste Reports.

Inspection Summary:

We arrived on site at 9:35 a.m. and met with Belton Rogers, the Plant Superintendant. The environmental contacts, Tom Craig and Jim Mantell, were both out of the office. We began with an opening conference to discuss environmental issues at the plant. The site has a stormwater permit and Belton is working on the required monitoring plan at the present time. A clean air inspector was recently inspecting the plant to check on the air quality permit compliance. An on-site wastewater treatment plant treats wastewater generated inside the plant and recirculates a large portion of it back into the adhesive used to form the boxes. Some treated wastewater is discharged to the sewer system under a discharge permit. Belton has also been working on this year's EPCRA report for the storage of diesel and sodium hydroxide for the wastewater treatment system.

Belton lead us on a tour of the plant beginning with some used shop towel collection containers. The containers were of the proper type and were kept closed, but were not labeled "Contaminated Shop Towels Only" as required for them to be exempt from the dangerous waste regulations; however it appears that the towels would not contain any hazardous waste. The printing machines are cleaned only with soap. No solvents are used in the plant.

In several locations there were grates on the floor to contain any liquids and direct them to the wastewater treatment area.

Near the wastewater treatment plant and within a secondary containment berm, the waste oil from the machines is stored in a large bin. It is properly labeled as "used oil only" and the funnel in the bung was padlocked. The used oil is picked up by Emerald Petroleum. Floor dry from spill cleanup is non-hazardous and disposed in the dumpster.

The sodium hydroxide is also stored within the bermed area in a bin. Recently the pH readings of the wastewater prior to treatment have been recorded. The pH was measured at between 8 and 10. Belton said that the company won an award for their wastewater recirculating system.

We went outside to the diesel storage area. A large diesel tank is stored within a fence, under cover, and with containment. Next to it was a large dumpster containing the filter cake from the wastewater treatment system. Belton stated that the filter cake has been tested and the company has the approvals to dispose of it into the dumpster since it is not hazardous waste.

A Safety Kleen parts washer is located in the maintenance area. The solvent is rarely changed. Safety Kleen changes the parts washer solvent on an on-call basis.

We reviewed the site records. The annual dangerous waste reports for 2000 and 2001 indicate that no regulated waste was generated. Safety Kleen manifests for the parts washer solvent were available for 1995 and 1996, but no parts washer solvent has been generated since then. The used solvent may be being managed under Safety-Kleen's continued use program so that no waste is generated.

The inspection concluded at 10:35 a.m.

Compliance Problems

The following conditions identified during the inspection on February 26, 2003, were not in compliance with Dangerous Waste and/or other environmental laws. Each problem is covered in three parts: (1) the citation from the regulations, (2) the specific observations from the inspection that highlight the problem, and (3) the corrective measures needed to fix the problem and achieve compliance. On the last page(s) of this report is a Compliance Certificate which again lists these compliance citations and directives in a table. That certificate also lists the deadlines for the corrective measures to be completed. The certificate explains how to complete the form and return it to the Department of Ecology.

- 1) No violations were observed during this inspection.

COMPLIANCE CERTIFICATE

Instructions: Return this Completed Form or Request an Extension -- Use this form to report if the action(s) needed to achieve compliance, identified during the inspection on February 26, 2003, have been completed. Complete the shaded portion of the table and mail a copy of this form to Victoria Sutton by (NA) at the following address: Washington Department of Ecology, Hazardous Waste and Toxics Reduction Program, Attention: Victoria Sutton, 3190 160th Avenue SE, Bellevue, WA, 98008.

An extension of the deadlines to achieve compliance may be requested. Please make a request in writing, including the reasons an extension is necessary and proposed date(s) for completion, and send it to Victoria Sutton before the date specified above. Ecology will provide a written approval or denial of your request.

*If you have any questions about information in this Compliance Report, please call:
Victoria Sutton at (425) 649-7277.*

The problems identified below must be corrected in order to be in compliance with Washington Dangerous Waste Regulations (Chapter 173-303 WAC), or other environmental laws or regulations. Please indicate the date each action is completed, or check the box under "Not Completed" and initial each item. Include any comments explaining the actions taken on a separate piece of paper.

1) No violations were observed during this inspection.

The Department of Ecology is an equal opportunity agency and does not discriminate on the basis of race, creed, color, disability, age, religion, national origin, sex, marital status, disabled veteran's status, Vietnam Era veteran's status or sexual orientation. If you have special accommodation needs or require this document in alternative format, please contact Victoria Sutton at (425) 649-7277 (Voice) or use the Washington State Relay operator by dialing either 711 or 1-800-833-6388 (TTY).